


Clean Fittings

High Flow Tube Butt Weld Gland


H-ZHG



Part No.	ZCR Size	T Tube O.D	d		d ₁		L		Working Pressure psig (bar)		
			mm	in.	mm	in.	mm	in.	NI	SS	CU
H-ZHG-6L15.2	1/4	3/8	6.35	0.25	7.9	0.31	15.2	0.60	3300 (227)		
H-ZHG-6L30.2							30.2	1.19			
H-ZHG-6L33.3							33.3	1.31			

High Flow Tube Butt Weld Reducer


H-ZR



Part No.	ZCR Size	T Tube O.D	d		d ₁		L		H	Working Pressure psig (bar)		
			mm	in.	mm	in.	mm	in.	in.	NI	SS	CU
H-ZR4-6	1/4	3/8	6.35	0.25	7.9	0.31	42.7	1.68	5/8	3300 (227)		

High Flow Tube Weld Reducer with Shoulder


H-ZR-A



Part No.	ZCR Size	T Tube O.D	d		d ₁		L		H	Working Pressure psig (bar)		
			mm	in.	mm	in.	mm	in.	in.	NI	SS	CU
H-ZR4-6A	1/4	3/8	6.35	0.25	7.9	0.31	43.4	1.71	5/8	3300 (227)		

High Flow Tube Butt Weld Bulkhead Connector

H-ZHBT



Part No.	ZCR Size	E Tube O.D.	d		d ₁		L		N		H	H ₁	Panel Hole size		Max. Panel Thickness		Working Pressure psig (bar)		
			mm	in.	mm	in.	mm	in.	mm	in.	in.	in.	mm	in.	mm	in.	NI	SS	CU
H-ZBT4-4 H-ZHBT4-6 H-ZBT4-4L50	1/4	3/8	6.35	0.25	7.9	0.31	59.9	2.36	33.0	1.30	3/4	3/4	14.5	0.57	11.1	0.44	3300 (227)		

Dimensions are reference only, subject to change.